ชื่อเรื่องวิทยานิพนธ์

ความแข็งแรงเฉือนคงค้างของดินเหนียวสีเขียวที่ถูก เฉือนในเหมืองแม่เมาะ

ผู้เขียน

นายนพคล มุ่งพยาบาล

ปริญญา

วิศวกรรมศาสตรมหาบัณฑิต (วิศวกรรมเหมืองแร่)

อาจารย์ที่ปรึกษาวิทยานิพนธ์

ผศ. คร. อัมรินทร์ บุญตัน

บทคัดย่อ

ปัญหาด้านเสถียรภาพผนังบ่อเหมืองของเหมืองแม่เมาะส่วนใหญ่เกิดจากชั้นที่ถูกเฉือนของ ดินเหนียวสีเขียว การศึกษาครั้งนี้เพื่อพยายามหาค่าความแข็งแรงเฉือนคงค้างของดินเหนียวสีเขียวที่ ถูกเฉือนเพื่อใช้ในการวิเคราะห์เสถียรภาพของผนังบ่อเหมือง

ได้ทำการเก็บตัวอย่างจำนวน 14 ตัวอย่าง จากชั้นที่ค่อนข้างบางของดินเหนียวสีเขียวที่ถูก เฉือน ในหน้างานบ่อเหมืองตะวันตกเฉียงใต้แทนที่จะเก็บจากหลุมเจาะ ได้ทำการศึกษาชนิดของแร่ ดินเหนียวของดินเหนียวสีเขียวที่ถูกเฉือนโดยวิธีการเลี้ยวเบนของรังสีเอกซ์ นอกจากนั้นยังศึกษา ข้อมูลของปริมาณเม็ดดินขนาดดินเหนียวและพิกัดอัตเตอร์เบิร์ก ในการศึกษาค่าความแข็งแรงเฉือน คงค้างได้ใช้วิธีการทดสอบแบบเฉือนโดยตรงหลายรอบ

ผลการศึกษาแสดงให้เห็นว่าดินเหนียวสีเขียวที่ถูกเฉือนประกอบด้วยแร่เคโอลิในต์และแร่ กลอไรต์เป็นหลักมีแร่อิลไลต์และแร่มอนต์โมริโลไนต์เล็กน้อย จากการศึกษาปริมาณเม็ดดินขนาด ดินเหนียวพบว่ามีปริมาณ 36.76-55.84 % จากการทดสอบหาพิกัดอัตเตอร์เบิร์ก มีค่าพิกัดเหลว 43.53-54.13 % , พิกัดพลาสติก 20.38-31.83 % และค่าดัชนีพลาสติก 19.18-28.79 % และจากการ ทดสอบโดยวิธีการเฉือนโดยตรงหลายรอบสามารถหาค่ามุมเสียดทานคงค้างได้ 9.6-14 องศา และมี ค่าเฉลี่ย 11.5 องศา จากการศึกษาไม่แสดงความสัมพันธ์ที่ชัดเจนระหว่างปริมาณเม็ดดินขนาดดิน เหนียว, ค่าพิกัดอัตเตอร์เบิร์กและค่ามุมเสียดทานคงค้างของดินเหนียวสีเขียวที่ถูกเฉือน

Thesis Title

Residual Shear Strengths of Sheared Green Clay in

Mae Moh Mine

Author

Mr. Noppadon Mungpayabal

Degree

Master of Engineering (Mining Engineering)

Thesis Advisor

Asst. Prof. Dr. Amarin Boonton

ABSTRACT

Most of pit slope stability problems at the Mae Moh Mine occurred on sheared layers of green clay. This research is the attempt to find out the proper residual shear strength value of the sheared green clay for pit slope analysis.

The fourteen samples were collected from the thin layers of sheared green clay at the southwest pit mine site instead of collecting them from the bore hole. The clay minerals of the sheared green clay were studies using an X - ray diffraction analysis method. The clay size fraction and the Atterberg limits were also studied. The multi-reversal direct shear tests were conducted to determine the residual shear strength values of the sheared green clay.

The results show that the sheared green clay were composed mostly of Kaolinite and Chrolite with some Illite and Montmorilonite. According to the soil fine analysis, the sheared green clay contain 36.76 - 55.84 % clay size. The results from Atterberg Limits tests indicate that the liquid limit is 43.53 - 54.13 %, plastic limit is 20.38 - 31.83 % and plastic index is 19.18 - 28.79 %. Corresponding to multi-reversal direct shear tests, the residual shear strength value of the sheared green clay in terms of friction angle is 9.6 - 14 degrees with 11.5 degrees on average. The study shows no distinct relationship between the clay fractions, the Atterberg limits and the residual friction angle of the sheared green clay.